

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, March 23, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak
START-USEPA
Situation Unit Leader



1. Talmadge Creek, snare boom observed in the culvert at A Drive.



2. Confluence no turbidity or sheen observed.



3. Ceresco Dam boom.



4. Ceresco Dam sheen collecting in boom.



5. Ceresco Dam boom.



6. MP15.75 boom deployed above the Battle Creek spillway.



7. MP14.75 C5 Boat Launch sheen observed.



8. MP14.75 C5 Boat Launch sheen observed.



9. MP14.75 C5 Boat Launch sheen observed.



10. Morrow Lake SWAT crews observed installing E4 control point.



11. MP37.75 sheen observed in the center channel.



12. Morrow Lake poling crew.



13. Morrow Lake poling crew.



14. Morrow Lake poling crew.